

Form Information

Form Name:	IHCDA BLN Pre-Bid Survey Results
Submission Date:	Jan 27, 2016 8:01:14 PM UTC

General Parcel Survey Information

Date of Survey	Jan 27, 2016
Name of Surveyor	John Lake
Applicant Name	City of Shelbyville
Property Address	607 E. Jackson Street Shelbyville IN
Image of Property	



Is the entry accessible? Yes

Pre-Bid Survey Form

NOTE:

BLN is responsible only for a visual and non-intrusive inspection not involving any testing. Further inspecting, testing, sampling, and/or remediation of any conditions inspected or noted in this report remain the sole responsibility of the owner.

POTENTIAL ASBESTOS-CONTAINING MATERIALS (ACM)	No
POLYCHLORINATED BIPHENYLS (PCBs)	No
Mercury light switches	No
Mercury-containing thermostats	Yes
Room	Living Room
Attach Image	



Mercury-containing gas pressure regulators

Yes

Room

Exterior/Yard

Attach Image



Batteries

No

Fluorescent, high-intensity discharge (HID), and low pressure sodium lamp bulbs

Yes

Room

Living Room

Attach Image



Refrigerant (found in air conditioners, refrigerators, freezers and dehumidifiers)

No

Smoke detectors	No
Fire extinguishers	No
Compressed gas cylinders	No
Electronics	No

Chemicals
Room
Attach Image

Yes
Living Room



Pesticides
Room
Attach Image

Yes
Living Room



Paints
Room
Attach Image

Yes
Multiple Rooms



Solvents

No

Used oil

No

Fuels and fuel oil tanks

No

Biological waste (vermin, pigeon excrement)

Yes

Room

Living Room

Attach Image



Medical waste (syringes)

No

Mechanical equipment (lawn mowers, etc.)

Yes

Room

Living Room

Attach Image



Scrap tires

Yes

Room

Living Room

Attach Image



Major appliances

No

Furniture

No

Mattresses

No

Controlled substances (pharmaceuticals or illegal substances)

No

Comments

Surveyor Comments

One story with basement
 Outside basement entry, Unsafe to enter basement
 Wood siding

Disclaimer/Limitation Language For Pre-Demolition Reports

This inspection report was performed on behalf of and solely for the exclusive use of the Indiana Housing And Community Development Agency ("IHCDA") and persons or organizations to whom the IHCDA wishes to make this report available. The services for this project have been performed in general conformance with the contract negotiated between IHCDA and Beam Longest & Neff ("BLN"). Any reliance on this report by a party other than IHCDA or agents of IHCDA shall be at the party's own risk. The observations set forth herein are valid only for the date and time noted herein. BLN specifically disclaims any responsibility for conditions of the subject property prior to or after the date and time set forth herein. BLN shall not be responsible for damages, consequential or otherwise, for contamination or conditions not clearly present on the day and time of the survey. The observations set forth herein are based exclusively upon a visual inspection of items and matters that are clearly visible, are outside of confined or inaccessible areas, and are identified on the checklist in the contract between IHCDA and BLN. BLN has not conducted any intrusive inspections, intrusive observations, testing or abatement of any item observed during the course of the survey or identified herein. The observations set forth in this Pre-Demolition Survey report shall not be construed as a recommendation for any specific action and shall not be construed as any form of a legal opinion.